bticino

Hotel Supervision Software

## 1   LIST OF CATALOGUE REFERENCES:

3546SW

2   ATTENTION

⚠ • Software is intended to manage up to 150 rooms.

⚠ • To ensure compatibility and optimal performance, it is necessary to upgrade system components according to the following table:

Software / Firmware	Required Version
Hotel Supervision	2.5.X or higher
MyHotel_Suite	5.0.7 or higher
MH201 Firmware	3.5.X or higher

⚠ NOTE: If you replace any MH201 with a new MH201 running Firmware version 3.5.X or higher, you must update all remaining MH201 units in the installation.

⚠ • To use the supervision system, you need to purchase the cards containing the unlocking codes.

⚠ • The password to enter the first time the software is started is "**admin**"

3   PC REQUIREMENTS

3.1   SUPERVISION SERVER

Requirement	Description
Operating System	Windows 10
Architecture	64bit
.Net framework	4.0 or higher
Processor	Performance equivalent to or better than intel core i7
RAM	8 GB but recommended 16 GB
Hard Disk	2 GB free
Display	1366 x 768 but recommended 1920 x 1080

3.2   SUPERVISION

Requirement	Description
Operating System	Windows 10
Architecture	64bit
.Net framework	4.0 or higher
Processor	Performance equivalent to or better than intel core i5
RAM	8 GB but recommended 16 GB
Hard Disk	2 GB free
Display	1366 x 768 but recommended 1920 x 1080