

## Release note for Kit Com. update package V02.01.14

- Com. kit management Software: V02.01.14
- Com. kit web page Software: V02.01.07
- Charge point Firmware : V01.19.02

This release note lists all the modifications made on this software since "KitCom-V02.00.02.zip"

### Com. kit management Software: V02.01.14

- **[BUG FIX]** Fixed a bug that prevented the user from logging in.
- **[BUG FIX]** Forced the restoration of the files Side1.csv and Side2.csv at the startup of the Com. kit management software in case of corruption.
- **[BUG FIX]** Fixed a bug that prevented the deletion of the web page logs.
- **[BUG FIX]** Fixed a bug that causes the deactivation of the socket(s) after the Factory Reset.
- **[BUG FIX]** Fixed a bug that prevented the KitCom to correctly perform the OCPP update procedure.
- **[BUG FIX]** Fixed a bug that prevented the KitCom to store the password used in the OCPP communication when the Security Profile is set to 2.
- **[BUG FIX]** Fixed a bug that causes the KitCom to reboot after 30 minutes when it is set in OCPP functioning mode and it is not connected to any WS.
- **[IMPROVEMENT]** After a Factory Reset the functioning mode will be reset to the Direct Charge one.
- **[IMPROVEMENT]** After a Factory Reset the ModBus address for the right side will be set to 1.
- **[IMPROVEMENT]** After a Factory Reset the ModBus address for the left side will be set to 2.
- **[IMPROVEMENT]** The Factory Reset is now available via physical button, too.
- **[IMPROVEMENT]** The Error 0013 handling has been improved.
- **[IMPROVEMENT]** Reduced the volume of the logs produced by the KitCom.

### Com. kit web page Software: V02.01.07

- **[BUG FIX]** Fixed a bug that prevented the KitCom to use the correct language in the login web page after this one has been changed.
- **[BUG FIX]** Fixed a bug that prevented the user to change the language of the web pages (and that always show them in English).
- **[BUG FIX]** Fixed a bug that prevented the KitCom to correct display the used time zone.
- **[BUG FIX]** Fixed typos in the translations.
- **[BUG FIX]** Fixed a bug that prevented the KitCom to correctly display the WiFi SSID parameter value in the Networks web page.
- **[BUG FIX]** Fixed a bug that prevented the KitCom to correctly display the instantaneous powers and their related unit of measurement in the Dashboard web page.
- **[BUG FIX]** Fixed a bug that prevented the KitCom to correctly localize the password change and Factory Reset web pages.
- **[BUG FIX]** Fixed a bug that prevented the KitCom to correctly handle some input form fields (e.g. email configuration).
- **[IMPROVEMENT]** The allowed special characters are now shown into the hint of the change password web page.

### Charge point Firmware: V01.19.02

- **[IMPROVEMENT]** Rewritten the calendar algorithm (calendar class).
- **[BUG FIX]** Fixed a bug for Heure creuse and heure pleine cost visualization.
- **[BUG FIX]** Fixed a bug that crashes BLE communication in "Resettable error" state.
- **[BUG FIX]** Fixed ecomode saving state in EEPROM.
- **[BUG FIX]** Fixed motor detection threshold.