




H = 25 mm		
	A	B
Pos	H1 mm	H2 mm
1	40	25
2	60	40
3	80	60
4	100	80
5		100



Pos	H = 25 mm		H = 40 mm	
	H1 mm	H2 mm	H1 mm	H2 mm
2	40	25	60	40
3	60	40	80	60
4	80	60	100	80
5	100	80		100



Pos	H = 25 mm		H = 40 mm		H = 60 mm	
	H1 mm	H2 mm	H1 mm	H2 mm	H1 mm	H2 mm
3	40	25	60	40	80	60
4	60	40	80	60	100	80
5	80	60	100	80		100



Pos	H = 60 mm		H = 80 mm	
	H1 mm	H2 mm	H1 mm	H2 mm
4	80	60	100	80
5	100	80		80