

IEC**IECEE**

®

TM

Ref. Certif. No.

CN52792-M2

IEC SYSTEM FOR MUTUAL RECOGNITION OF TEST CERTIFICATES FOR ELECTRICAL EQUIPMENT
(IECEE) CB SCHEME**CB TEST CERTIFICATE**

Product

Flush-type Rocker Two-way Switch with Lamp; Flush-type Rocker Two-way Switch; Flush-type
Rocker Single-pole Switch; Flush-type Rocker Two-circuit Switch with a Common Incoming Line
Switch

Name and address of the applicant

Legrand Intelligent Electrical (Huizhou) Co., Ltd.
Bldg. B1-B3, East No.39 Hechang 6th Rd., HZZK Hi-tech Industrial
Development Zone, Huizhou, Guangdong, P.R.China

Name and address of the manufacturer

LEGRAND FRANCE
128, Avenue du Maréchal de Lattre de Tassigny 87045 LIMOGES
Cedex-FRANCE

Name and address of the factory

Legrand Intelligent Electrical (Huizhou) Co., Ltd.
Bldg. B1-B3, East No.39 Hechang 6th Rd., HZZK Hi-tech Industrial
Development Zone, Huizhou, Guangdong, P.R.China

Note: When more than one factory, please report on page 2

Ratings and principal characteristics

See appendix

Trademark / Brand (if any)

Graphic Trademark, See the report

Customer's Testing Facility (CTF) Stage used

N/A

Model / Type Ref.

See appendix

Additional information (if necessary may also be
reported on page 2)A sample of the product was tested and found
to be in conformity with

IEC 60669-1:2017

As shown in the Test Report Ref. No. which
forms part of this Certificate

CVC2020-1395-M2

This CB Test Certificate is issued by the National Certification Body .

CHINA QUALITY CERTIFICATION CENTRE

Section 9, No. 188 Nansihuan Xilu, Beijing 100070 P. R. China

Tel: +86-10-83886666 Fax: +86-10-83886282

website: <http://www.cqc.com.cn>

Date:

Jul.18,2022

Signature:

谢肇旭

Xie ZhaoXu

**CB 0069661**

1. Flush-type Rocker Two-way Switch with Lamp
2. Flush-type Rocker Two-way Switch
3. Flush-type Rocker Single-pole Switch

1. 281046MW, 281046MG, 281046MB, 281046DS, 281046CH, 281046DB, 281046BA, 281046BB, 281046MWSG, 281046MGSG, 281046MBSG, 281046DSSG, 281046CHSG, 281046DBSG, 281046BASG, 281046BBSG, 281246MW, 281246MB, 281246DS, 281246CH, 281246DB, 281246BA, 281246BB 16AX 250V~ ;

2. 281001MW, 281003MW, 281005MW, 281007MW, 281011MW, 281013MW, 281015MW, 281001MG, 281003MG, 281005MG, 281007MG, 281011MG, 281013MG, 281015MG, 281001MB, 281003MB, 281005MB, 281007MB, 281011MB, 281013MB, 281015MB, 281001DS, 281003DS, 281005DS, 281007DS, 281011DS, 281013DS, 281015DS, 281001CH, 281003CH, 281005CH, 281007CH, 281011CH, 281013CH, 281015CH, 281001DB, 281003DB, 281005DB, 281007DB, 281011DB, 281013DB, 281015DB, 281001BA, 281003BA, 281005BA, 281007BA, 281011BA, 281013BA, 281015BA, 281001BB, 281003BB, 281005BB, 281007BB, 281011BB, 281013BB, 281015BB, 281001MWSG, 281003MWSG, 281005MWSG, 281007MWSG, 281011MWSG, 281013MWSG, 281015MWSG, 281001MGSG, 281003MGSG, 281005MGSG, 281007MGSG, 281011MGSG, 281013MGSG, 281015MGSG, 281001MBSG, 281003MBSG, 281005MBSG, 281007MBSG, 281011MBSG, 281013MBSG, 281015MBSG, 281001DSSG, 281003DSSG, 281005DSSG, 281007DSSG, 281011DSSG, 281013DSSG, 281015DSSG, 281001CHSG, 281003CHSG, 281005CHSG, 281007CHSG, 281011CHSG, 281013CHSG, 281015CHSG, 281001DBSG, 281003DBSG, 281005DBSG, 281007DBSG, 281011DBSG, 281013DBSG, 281015DBSG, 281001BASG, 281003BASG, 281005BASG, 281007BASG, 281011BASG, 281013BASG, 281015BASG, 281001BBSG, 281003BBSG, 281005BBSG, 281007BBSG, 281011BBSG, 281013BBSG, 281015BBSG 16AX 250V~, 281051MW, 281053MW, 281055MW, 281051MG, 281053MG, 281055MG, 281051MB, 281053MB, 281055MB, 281051DS, 281053DS, 281055DS, 281051CH, 281053CH, 281055CH, 281051DB, 281053DB, 281055DB, 281051BA, 281053BA, 281055BA, 281051BB, 281053BB, 281055BB, 281051MWSG, 281053MWSG, 281055MWSG, 281051MGSG, 281053MGSG, 281055MGSG, 281051MBSG, 281053MBSG, 281055MBSG, 281051DSSG, 281053DSSG, 281055DSSG, 281051CHSG, 281053CHSG, 281055CHSG, 281051DBSG, 281053DBSG, 281055DBSG, 281051BASG, 281053BASG, 281055BASG, 281051BBSG, 281053BBSG, 281055BBSG 20AX 250V~ ;

Page 1 of 2

Additional information (if necessary)

Date: Jul.18,2022

Signature:



Xie ZhaoXu

3. 281000MW, 281004MW, 281006MW, 281010MW, 281014MW, 281000MG, 281004MG, 281006MG, 281010MG, 281014MG, 281000MB, 281004MB, 281006MB, 281010MB, 281014MB, 281000DS, 281004DS, 281006DS, 281010DS, 281014DS, 281000CH, 281004CH, 281006CH, 281010CH, 281014CH, 281000DB, 281004DB, 281006DB, 281010DB, 281014DB, 281000BA, 281004BA, 281006BA, 281010BA, 281014BA, 281000BB, 281004BB, 281006BB, 281010BB, 281014BB, 281000MWSG, 281004MWSG, 281006MWSG, 281010MWSG, 281014MWSG, 281000MGSG, 281004MGSG, 281006MGSG, 281010MGSG, 281014MGSG, 281000MBSG, 281004MBSG, 281006MBSG, 281010MBSG, 281014MBSG, 281000DSSG, 281004DSSG, 281006DSSG, 281010DSSG, 281014DSSG, 281000CHSG, 281004CHSG, 281006CHSG, 281010CHSG, 281014CHSG, 281000DBSG, 281004DBSG, 281006DBSG, 281010DBSG, 281014DBSG, 281000BASG, 281004BASG, 281006BASG, 281010BASG, 281014BASG, 281000BBSG, 281004BBSG, 281006BBSG, 281010BBSG, 281014BBSG, 281002MW, 281012MW, 281002MG, 281012MG, 281002MB, 281012MB, 281002DS, 281012DS, 281002CH, 281012CH, 281002DB, 281012DB, 281002BA, 281012BA, 281002BB, 281012BB, 281002MWSG, 281012MWSG, 281002MGSG, 281012MGSG, 281002MBSG, 281012MBSG, 281002DSSG, 281012DSSG, 281002CHSG, 281012CHSG, 281002DBSG, 281012DBSG, 281002BASG, 281012BASG, 281002BBSG, 281012BBSG 16AX 250V~, 281050MW, 281054MW, 281050MG, 281054MG, 281050MB, 281054MB, 281050DS, 281054DS, 281050CH, 281054CH, 281050DB, 281054DB, 281050BA, 281054BA, 281050BB, 281054BB, 281050MWSG, 281054MWSG, 281050MGSG, 281054MGSG, 281050MBSG, 281054MBSG, 281050DSSG, 281054DSSG, 281050CHSG, 281054CHSG, 281050DBSG, 281054DBSG, 281050BASG, 281054BASG, 281050BBSG, 281054BBSG, 281052MW, 281052MG, 281052MB, 281052DS, 281052CH, 281052DB, 281052BA, 281052BB, 281052MWSG, 281052MGSG, 281052MBSG, 281052DSSG, 281052CHSG, 281052DBSG, 281052BASG, 281052BBSG 20AX 250V~

Ratings : 1. 16AX 250V~

2. 16AX 250V~, 20AX 250V~

3. 16AX 250V~, 20AX 250V~

Page 2 of 2

Additional information (if necessary)

Date: Jul.18,2022

Signature:

谢肇煦

Xie ZhaoXu