



Legrand cabling system, LCS³ fiber optic pigtails and fan-out units



Selection chart p. 966-967

Pack	Cat.Nos		Core pigtails
			LSZH For making quick, reliable and high-performance fiber optic cable connections on site: - OM2/OM3/OM4 IL Typical/Master = 0.15 dB - OS2 IL Typical/Master = 0.18 dB Compatible with all commercially-available splicers
			50/125 µm - OM3 (PC) SC connectors LC connectors ST connectors
1	0 322 20	0 322 23	1 m 2 m 0 322 21 0 322 24 0 322 22
1	0 322 30	0 322 33	
1	0 322 31	0 322 34	
1	0 322 32		50/125 µm - OM4 (PC) SC connectors LC connectors ST connectors
			9/125 µm - OS2 (APC or UPC) - OS1 compatible SC-APC connectors SC-UPC connectors LC-APC connectors LC-UPC connectors ST-UPC connectors
1	0 322 40	0 322 45	
1	0 322 41	0 322 46	
1	0 322 42	0 322 48	
1	0 322 43	0 322 47	
1	0 322 44		
			Sets of 12 LC pigtails 1m length - 12 different colors 12 OS2 LC-UPC pigtails 12 OM3 LC-UPC pigtails 12 OM4 LC-UPC pigtails
1	0 326 24		
1	0 326 26		
1	0 326 71		
			Heat-shrinkable sleeve for pigtails 40 mm - pack of 50 sleeves
1	0 327 44		
			Fan-out units For 900 µm sheathing of optical fibers Take 250 µm fiber diameters 6-fiber fan-out unit 12-fiber fan-out unit
1	0 330 48		
1	0 330 49		

Legrand cabling system, LCS³ fiber optic case and quick-connect connectors



Pack	Cat.Nos	Tool case for preparing optical fiber for quick-connect fiber optic connectors
1	0 322 70	Provides the tools required for preparing optical cables, for carrying out initial tests of the connection of fibers to connectors and accessories for easy connection in all situations Comprises: - Precision cleaver - Kevlar stripping and cutting tool - Visual fault locator - Installation instructions and video - Accessories (cleaners, felt tip pen, bin, etc)
		Quick-connect connectors Connection can be made with case Cat.No 0 322 70 Quick-connect, reliable and reusable up to 5 times To be used to lock the fiber inside the connector An indicator light is used to test the connection No glue or polishing needed Can be installed on 900 µm fiber optics For 250 µm fiber, use the special tubes supplied with the connectors; typical IL: multimode OM3/OM4 = 0.1 dB and single-mode OS2 = 0.2 dB (PC) and 0.3 dB (APC)
		OM3/OM4 multimode connectors Set of 12 connectors LC PC 50/125 µm, 900/250 µm SC PC 50/125 µm, 900/250 µm
12	0 322 71	
12	0 322 72	
		OS2 single-mode connectors Set of 12 connectors LC UPC 9/125 µm, 900/250 µm SC UPC 9/125 µm, 900/250 µm SC APC 9/125 µm, 900/250 µm
12	0 322 73	
12	0 322 74	
12	0 322 75	
		Fiber optic cleaning accessories 1 0 322 83 MPO/MTP ⁽¹⁾ ferrule cleaner 1 0 322 81 LC ferrule cleaner (PC/APC) 1 0 322 82 SC ferrule cleaner (PC/APC) 1 0 322 78 Cleaning spray

1: MTP is a registered trademark of US Conec Ltd