



	21~30V $\overline{\text{---}}$,via KNX BUS
	19.5mA max
$X =$	X = 2
	4 x (\varnothing . 6mm $<$ $\frac{8}{\text{mm}}$ $<$ \varnothing . 8mm)
	-5°C \rightarrow +45°C

